


Report No. : FR932302-01

Appendix B. Setup Photographs

<Conducted Emission> Mode 4



Front View



Rear View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7WR7310 Page Number : B1 of B4
Report Issued Date : Apr. 06, 2009
Report Version : Rev. 01





Report No.: FR932302-01



Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7WR7310 Page Number : B2 of B4
Report Issued Date : Apr. 06, 2009
Report Version : Rev. 01





Report No.: FR932302-01

<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7WR7310 Page Number : B3 of B4
Report Issued Date : Apr. 06, 2009
Report Version : Rev. 01





Report No.: FR932302-01



Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7WR7310 Page Number : B4 of B4
Report Issued Date : Apr. 06, 2009
Report Version : Rev. 01