

Appendix B. Setup Photographs

<Conducted Emission>





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WH7CMA1000 Page Number : B1 of B2
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR750402A




<Radiated Emission>





HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WH7CMA1000 Page Number : B2 of B2
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR750402A