3. Internal Photograph of EUT

Brand Name: Longcheer; Model Name: LCT_L6352_A01

Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 12 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01



Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 13 of 31 Report Issued Date : Jul. 09, 2015 Report Version : Rev. 01



Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 14 of 31 Report Issued Date : Jul. 09, 2015 Report Version : Rev. 01



Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 15 of 31 Report Issued Date : Jul. 09, 2015 Report Version : Rev. 01


Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 16 of 31 Report Issued Date : Jul. 09, 2015 Report Version : Rev. 01



Report No.: EP542307




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 17 of 31 Report Issued Date : Jul. 09, 2015 : Rev. 01

Report Version



Report No.: EP542307




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 18 of 31 Report Issued Date : Jul. 09, 2015

: Rev. 01 Report Version






Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 19 of 31 Report Issued Date : Jul. 09, 2015 : Rev. 01 Report Version




Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 20 of 31 Report Issued Date : Jul. 09, 2015 : Rev. 01 Report Version




Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 21 of 31 Report Issued Date : Jul. 09, 2015 : Rev. 01 Report Version




Report No.: EP542307




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 22 of 31 Report Issued Date : Jul. 09, 2015 : Rev. 01 Report Version






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 23 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01

Report No.: EP542307




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 24 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01

Report No.: EP542307




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 25 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01

Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 26 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01

Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 27 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01




Report No.: EP542307



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 28 of 31 Report Issued Date : Jul. 09, 2015 Report Version : Rev. 01


Report No.: EP542307



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 29 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01







SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 30 of 31 Report Issued Date : Jul. 09, 2015 Report Version : Rev. 01

Report No.: EP542307





 ${\it SPORTON\ INTERNATIONAL\ (KUNSHAN)\ INC.}$

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7-LCT-L6352 Page Number : 31 of 31
Report Issued Date : Jul. 09, 2015
Report Version : Rev. 01