
3. Internal Photograph of EUT


Brand Name: Longcheer; Model Name: CMA1000

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 10 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 11 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 12 of 37
Report Issued Date : Jun. 28, 2017

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 13 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 14 of 37
Report Issued Date : Jun. 28, 2017




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 15 of 37
Report Issued Date : Jun. 28, 2017

Brand Name: Longcheer; Model Name: CMA1000




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 16 of 37
Report Issued Date : Jun. 28, 2017

Report No.: EP750402



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 17 of 37
Report Issued Date : Jun. 28, 2017


Report No.: EP750402



Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 18 of 37
Report Issued Date : Jun. 28, 2017

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 19 of 37
Report Issued Date : Jun. 28, 2017

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 20 of 37
Report Issued Date : Jun. 28, 2017

Brand Name: Longcheer; Model Name: CMA1000




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 21 of 37
Report Issued Date : Jun. 28, 2017

Brand Name: Longcheer; Model Name: CMA1000




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 22 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 23 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Brand Name: Longcheer; Model Name: CMA1000




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 24 of 37 Report Issued Date : Jun. 28, 2017

Report No.: EP750402



Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 25 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 26 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01


Report No.: EP750402



Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 27 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Report No.: EP750402



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 28 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Report No.: EP750402



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 29 of 37
Report Issued Date : Jun. 28, 2017

Report No.: EP750402



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 30 of 37
Report Issued Date : Jun. 28, 2017

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 31 of 37 Report Issued Date : Jun. 28, 2017




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 32 of 37
Report Issued Date : Jun. 28, 2017

Brand Name: Longcheer; Model Name: CMA1000




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 33 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Brand Name: Longcheer; Model Name: CMA1000




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 34 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Report No.: EP750402




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 35 of 37 Report Issued Date : Jun. 28, 2017



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 36 of 37
Report Issued Date : Jun. 28, 2017

Report No.: EP750402



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WH7CMA1000 Page Number : 37 of 37
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01