

## Appendix D. Setup Photographs

## <Conducted Emission>





SPORTON International Inc.
TEL: 886-3-327-3456
FAX: 886-3-328-4978
FCC ID: WH7CMA1000

Page Number : D1 of D2
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01


Report No.: FR750402B

Report Template No.: BU5-FR15CBT4.0 Version 2.0




## <Radiated Emission>

LF



HF



SPORTON International Inc.
TEL: 886-3-327-3456
FAX: 886-3-328-4978
FCC ID: WH7CMA1000

Page Number : D2 of D2
Report Issued Date : Jun. 28, 2017
Report Version : Rev. 01

Report No.: FR750402B

Report Template No.: BU5-FR15CBT4.0 Version 2.0