DK TECHNOLOGY (HK) CO., LTD

FCCID: WH0-WM-88

July 15, 2008.

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

I would like to confirm this device (FCCID: WH0-WM-88) does not have tune up information because the tune up is fixed by the manufacturer. Therefore, the user cannot tune up the device.

Sincerely,

DK TECHNOLOGY (HK) CO., LTD

Leo Qing General Manager