

這個獨特的通話裝置提供了摩托車騎士安全的手機通信方式 ,優異的音質和與後座成員更容易的溝通方式。增加了安全 帽的功能性,騎車安全性和乘客舒適度。





03 接聽來電時:按一下接聽/掛斷鍵。

耳機自動連接上配對過的手機: 開機後自動會連接上配對 過的手機,若沒成功也可以按壓一下接聽/掛斷鍵去連接配 對過的手機。













產品名稱:安全帽用藍芽通話裝置

低電壓指示:藍燈,指示音每五秒都一聲

產品型號:ST-1000/ST-1001

4. 檔案支援:A2DP,HFP,HSP

. 電源:3V(4號鹼性電池X2)

. 持續通話:15hr

10. 前後對講模式:全雙工

2 適用於全罩與3/4安全帽


14. 認證:CE、FCC、NCC、TELEC

9. 藍芽版本2.0

3. 防潑水設計









電話:+886-2-2763-8627 傳真: + 8 8 6 - 2 - 2 7 6 3 - 8 4 8 5 聯 絡 人 : 龔 迺 睛

Technology - Hidden microphone provides clearer sound quality.

Convenience – Receive incoming calls automatically while riding, and avoid traffic violations (depending on the cell phone). Safety - Provides an easy, clear and secure way for rider and

User-Friendly – This device can be installed damage-free on an

existing helmet without using glue. It takes less than one minute to

passenger to communicate with each other.



保固期:六個月 保證卡提供自交貨日起六個月内維修保固。 產品於保固期内正常使用下,如發生故障,則冤費維修, 但因未照說明書使用本產品、人為因素包括強力撞擊、重 摔、不當敲擊、接觸磁性物質、電擊、浸水、火燒、曝曬 於高溫、冷凍、擅自拆裝添附修改或天災地變,不在此限

主機上之產品序號應和產品保證書相同。 保證書若有遺失,恕不補發。 保證書未加蓋經銷商印章或塗改時無效。 若需維修時,未能出示保證卡時或保證期限已過期,需酌 收維修費用。



對過的手機,若沒成功也可以再次按下通話鍵連結配對

2.當使用藍芽功能接聽手機時,無法與後座乘客對話。 本產品為防潑水設計,若有雨水不慎滲入,請擦拭後等

待風乾後再使用。 4.内外耳機應先行定位再開啓,以冤產生雜音等干擾現象。 5.若安全帽尺寸與使用者不符,收音效果將打折扣。 6.將魔鬼粘母片貼於安全帽内側耳部凹槽後,安插内部耳 機時,麥克風孔應朝向正前方已達到最佳的收音效果。



國家通訊傳播委員會NCC Statement:


根據交通部低功率電波輻射性電機管理辦法 規定:


第十二條 經型式認證合格之低功率射頻電機,非經許可,公司 、商號或使用者均不得擅自變更頻率、加大功率或變 更原設計之特性及功能。


第十四條 低功率射頻電機之使用不得影響飛航安全及干擾合法 通信;經發現有干擾現象時,應立即停用,並改善至無干擾時方得繼續使用。前項合法通信,指依電信法 規定作業之無線電通信。 低功率射頻電機須忍受合法通信或工業、科學及醫療 用電波輻射性電機設備之干擾。













This product is a 2-in-1 communication device which provides customers with a new, safe, more functional, and zero distant communication. Cell phone calls can be delivered through this Bluetooth device when a user is wearing a helmet because the device is clipped onto the helmet. Additionally, there is a second device connected to the back of the helmet which allows a rider and a passenger to communicate with each other. Whenever there is an incoming call, the first device can disconnect the second device and switch to the incoming call at the push of a button.



Entertainment - This product also has a stereo device which can be support the MP3 function of the cell phone. This unique device provides motorcyclists not only with good sound quality communication, but also provides easy communication with the passenger. It makes a helmet become more useful while also creating a safer, more comfortable environment for both the rider and the passenger.


install or remove.











Follow the pairing instructions for the first use. After that the unit will pair automatically. If not, press the Talk key.

























3F., No.141, Sec. 1, Keelung Rd., Sinyi District, Taipei City 110, Taiwan (R.O.C.) TEL: + 8 8 6 - 2 - 2 7 6 3 - 8 6 2 7 + 8 8 6 - 2 - 2 7 6 3 - 8 6 3 7

FAX:+ 8 8 6 - 2 - 2 7 6 3 - 8 4 8 5

Contact: A m y K u n g

E-Mail:amy.kung@tw-cre.com

6 months warranty period is effective from the date of warranty situations occur: Damages caused by improper use without following the

instruction of User Manual, human factor, including heavy strike, falling, inappropriate hit, contact with magnetic material, electric shock, water immersion, fire burning, high-temperature exposure, freeze, disassembly or self change parts, natural disaster. This warranty card is only one certification for this product. If this warranty card is lost, it cannot be provided again. When you deliver product for repair, we will consider charging the expense of maintenance and material if exceeding the warranty period or damaged by human factor.

1. Follow the pairing instructions for the first use. After that the unit will pair automatically. If not, press the Talk key. 2. When switching to Bluetooth mode, users cannot communicate with passengers at the same time, and vice versa.

off and let it dry. 4.Two earphones should be positioned separately before operation, or noise might occur

5.If the size of the helmet were not suitable for the user, sound quality would be affected. 6. After placing headphones in the helmet by adhering loop sides of Velcro, please make sure the microphone open forward in order to reach the best result.

RISK OF EXPLOSION IF BATTERY IS REPLACED BY AN INCORRECT TYPE, DISPOSE OF USED BATTERIES ACCORDING TO THE INSTRUCTIONS.

Federal Communications Commission (FCC) Statement

You are cautioned that changes or modifications not compliance could void the user's authority to operate the equipment.

15.105(b) This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation.

interference to radio or television reception, which can be determined

-Consult the dealer or an experienced radio/TV technician for help.

This equipment generates, uses and can radiate radio frequency

Operation is subject to the following two conditions: instructions, may cause harmful interference to radio communica
1) this device may not cause interference and tions. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful

2) this device must accept any interference, including interference that may cause undesired operation of the device.

by turning the equipment off and on, the user is encouraged to try correct the interference by one or more of the following measures: -Reorient or relocate the receiving antenna.

FCC RF Radiation Exposure Statement: This equipment complies with FCC radiation exposure limits set forth Increase the separation between the equipment and receiver.

-Connect the equipment into an outlet on a circuit different from that transmitter must not be co-located or operating in conjunction with