

Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WIQCAT07 Page Number : D1 of D2
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01

Report No.: FA982012



Report No.: FA982012

Antenna Location:




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WIQCAT07 Page Number : D2 of D2
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01



Report No.: FA982012

Appendix E. **Test Setup Photos**



Right Cheek


Right Tilted




Left Cheek



Left Tilted



Face of the DUT with Phantom 2.0 cm Gap



Bottom of the DUT with Phantom 2.0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WIQCAT07

Page Number : E1 of E1 Report Issued Date: Oct. 06, 2009 Report Version : Rev. 01