

Report No. : FR982012


Appendix B. Setup Photographs

<Conducted Emission>

Mode 2



Front View



Rear View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WIQCAT07 Page Number : B1 of B4
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01





Report No.: FR982012



Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WIQCAT07 Page Number : B2 of B4
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01





Report No. : FR982012

<Radiated Emission>



Front View



Rear View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WIQCAT07 Page Number : B3 of B4
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01





Report No.: FR982012



Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WIQCAT07 Page Number : B4 of B4
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01