

Report No. : FG982012

## Appendix B. Setup Photographs

<Radiated Emission>
GSM Link Mode



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WIQCAT07 Page Number : B1 of B3
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01



Report No.: FG982012



Remote View

## **GSM + Bluetooth Link Mode**



Front View


SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WIQCAT07 Page Number : B2 of B3
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01



**Report No.: FG982012** 

Rear View





Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WIQCAT07 Page Number : B3 of B3
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01