

Report No. : FD982012


Appendix B. Setup Photographs

<Conducted Emission>

Mode 2



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WIQCAT07

: B1 of B4 Page Number Report Issued Date: Oct. 06, 2009 Report Version : Rev. 01





Report No.: FD982012



Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WIQCAT07 Page Number : B2 of B4
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01






Report No.: FD982012

<Radiated Emission>

Mode 1



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WIQCAT07 Page Number : B3 of B4
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01





Report No.: FD982012



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WIQCAT07 Page Number : B4 of B4
Report Issued Date : Oct. 06, 2009
Report Version : Rev. 01