Cet appareil numerique 01288 interference that may cause undesired operation of this device, cause interference, $\overline{\omega}$ digital apparatus complies d e and la classe (2) thsi device must accept any inteference, \Box est conforme with Canadian مع <u>___</u> ICES-003. 11 0 T 11 E

Operation is subject to the fllowing two

This device complies

with Part 15


0 f

FCC Rules and RSS-Gen of IC Rules.

condition: (1) this device may not

including

NMB-003 du Canada



Sankyo

MODEL No.

ICI3Q8-5293

R-8030001 nidec sankyo corporation made in Japan pat. Pend.

Model Rev
0 1 0 2 0 3 0 4 0 5
0 6 0 7 0 8 0 9 1 0
(A) B C D E

100-240V 0.53-0.31A 50/60Hz





CAUTION: For continued protect-ion against risk of fire, replace only with same type (T2.5AL/250V) and rating of fuse.

Double pole/neutral fusing

USB Serial Number e8060001

FCC ID:WJ6-308529301A IC No:7863A-308529301A