Test report No. : 28KE0126-HO-01-C-R1

 Page
 : 13 of 24

 Issued date
 : August 4, 2008


 Revisd date
 : August 21, 2008


 FCC ID
 : WJ6-3Q8529301A

APPENDIX 1: Photographs of test setup

Conducted emission







UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 28KE0126-HO-01-C-R1


Page : 14 of 24 : August 4, 2008 : August 21, 2008 : WJ6-3Q8529301A **Issued date** Revisd date FCC ID

Radiated emission (below 30MHz) Front









UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


: 28KE0126-HO-01-C-R1 Test report No.

Page : 15 of 24 : August 4, 2008 : August 21, 2008 : WJ6-3Q8529301A **Issued date** Revisd date FCC ID

Radiated emission (above 30MHz) Front







UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124