
FCC ID : WJ6-ICM0M001A-M Test report No. : 30DE0267-YK-01-R1

Page : 11 of 26

Issued date : December 28, 2009

Conducted emission





UL Japan, Inc. Yamakita EMC Lab.


907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN


FCC ID : WJ6-ICM0M001A-M $Test\ report\ No.\ :\ 30DE0267\text{-}YK\text{-}01\text{-}R1$

: 12 of 26 Page

: December 28, 2009 Issued date

Radiated emission (9kHz-30MHz, 1/2)





UL Japan, Inc.


Yamakita EMC Lab.907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN


FCC ID : WJ6-ICM0M001A-M Test report No. : 30DE0267-YK-01-R1

Page : 13 of 26

Issued date : December 28, 2009

Radiated emission (30MHz-1000MHz, 2/2)





UL Japan, Inc. Yamakita EMC Lab.

907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN

FCC ID : WJ6-ICM0M001A-M Test report No. : 30DE0267-YK-01-R1

Page : 14 of 26


Issued date : December 28, 2009

Pre-check of the worst position (Antenna)


X-axis



Y-axis



Z-axis



UL Japan, Inc. Yamakita EMC Lab.

907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN


FCC ID : WJ6-ICM0M001A-M Test report No. : 30DE0267-YK-01-R1

Page : 15 of 26

Issued date : December 28, 2009

Pre-check of the worst position (Module)


X-axis



Y-axis



Z-axis



UL Japan, Inc. Yamakita EMC Lab.

907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN