Test report No. : 11439195H-B-R1

: 17 of 19 Page

Issued date : December 6, 2016 FCC ID : WKE-722011

## **APPENDIX 3: Photographs of test setup**

### **Radiated Emission**




Photo 1




Photo 2

### UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11439195H-B-R1 Page : 18 of 19

Issued date : December 6, 2016 FCC ID : WKE-722011

### **Radiated Emission**




Photo 1



Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11439195H-B-R1 Page : 19 of 19

Issued date : December 6, 2016 FCC ID : WKE-722011

### **Worst Case Position**

### ANT

Below 1GHz Horizontal: Z-axis / Vertical: Y-axis Above 1GHz

Horizontal: Y-axis / Vertical: Y-axis

X-axis


#### Sterter Unit Below 1GHz


Horizontal: X-axis / Vertical: Z-axis


Above 1GHz

Horizontal: Y-axis / Vertical: Z-axis













**End of Report** 

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124