

Report No. : FR4D3129-01

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973






1 Photographs of Conducted Emissions Test Configuration

(Mode 1)



Report No. : FR4D3129-01

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A7

Report Version

: Rev. 02





Report No. : FR4D3129-01



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973






2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A7

Report Version

: Rev. 02

Report No. : FR4D3129-01




FCC Test Report

Report No. : FR4D3129-01

For radiated emissions 30MHz~1GHz

(Mode 1)



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7

Report Version : Rev. 02




CC Test Report No.: FR4D3129-01

For radiated emissions above 1GHz

(Mode 1)



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A7 TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973








Report No. : FR4D3129-01

EUT take a close-up



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A7

Report Version : Rev. 02