



### A.3 EMISSION LIMITATIONS MEASUREMENT

Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
Frequency		TX 5180MHz	
Cable Loss	1.6dB	Test Voltage	AC 120V, 60Hz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3





**AUDIX Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303



Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
Cable Loss	1.6dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			Test Voltage AC 120V, 60Hz
			3






**AUDIX Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan


Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
Cable Loss	1.6dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n)	(Note: "n" is antenna number)	Test Voltage	AC 120V, 60HZ
			3




**AUDIX Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303




Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.6dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			Test Voltage AC 120V, 60HZ
			3




**AUDIX Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303




Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.6dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			Test Voltage AC 120V, 60HZ
			3




**AUDIX Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303




Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.6dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3




**AUDIX Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303




Test Date	2016/06/14	Temp./Hum.	26°C/54%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		





**AUDIX Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303



Test Date	2016/06/14	Temp./Hum.	26°C/54%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5600MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		







**AUDIX Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan


Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2016/06/14	Temp./Hum.	26°C/54%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3






Test Date	2016/06/14	Temp./Hum.	26°C/54%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5720MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3



**AUDIX Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan


Tel: +886 2 26099301  
 Fax: +886 2 26099303




**AUDIX Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2016/06/14	Temp./Hum.	26°C/54%
Mode	802.11a	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		






**AUDIX Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan


Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2016/06/14	Temp./Hum.	26°C/54%
Mode	802.11a	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5785MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		



**AUDIX Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303



Test Date	2016/06/14	Temp./Hum.	26°C/54%
Mode	802.11a	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			Test Voltage AC 120V, 60HZ
			3

