1. External Photograph of EUT

Brand Name: 富士ソフト株式会社 / Model Name: WM340

Report No.: EP233002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 1 of 31

Report No.: EP233002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 2 of 31



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 3 of 31
Report Issued Date : May 30, 2012

Report Version : Rev. 01

Report No.: EP233002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 4 of 31
Report Issued Date : May 30, 2012

: Rev. 01

Report Version



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 5 of 31
Report Issued Date : May 30, 2012

Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 6 of 31

2. Photograph of Accessory

Brand Name: 富士ソフト株式会社 / Model Name: WM340

Report No.: EP233002

List of Accessory:

Specification of Accessory		
IAC Adapter	Brand Name	富士ソフト株式会社
	Model Name	STC-A2205I1500-M5
IBattery	Brand Name	富士ソフト株式会社
	Model Name	LB2930-01

Remark: For accessories equipped with this EUT, please refer to the following photos.

 ${\it SPORTON\ INTERNATIONAL\ (KUNSHAN)\ INC.}$

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 7 of 31
Report Issued Date : May 30, 2012
Report Version : Rev. 01

Report No.: EP233002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 8 of 31


Report No.: EP233002



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 9 of 31
Report Issued Date : May 30, 2012

Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : 10 of 31
Report Issued Date : May 30, 2012
Report Version : Rev. 01