


Report No. : FA230705

Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM320 Page Number : D1 of D1
Report Issued Date : Apr. 10, 2012
Report Version : Rev. 01



Report No. : FA230705

Appendix E. **Test Setup Photos**



Direct Laptop Plug-in for USB Configuration 1 (Horizontal Up with Phantom 5 mm Gap)



USB Cable Plug-in for USB Configuration 2 (Horizontal Down with Phantom 5 mm Gap)



USB Cable Plug-in for USB Configuration 3 (Vertical Front with Phantom 5 mm Gap)



Direct Laptop Plug-in USB Configuration 4 (Vertical Back with Phantom 5 mm Gap)



Direct Laptop Plug-in for USB Configuration 5 (Tip Mode with Phantom 5 mm Gap)

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM320

Page Number : E1 of E1 Report Issued Date: Apr. 10, 2012

: Rev. 01 Report Version