





Date Date Date Date Date Date Date Date	Approvals	o pulk	HBP3008 Omnibar	HBP3008 Omnibar SB1 Subwoofer Amplifier Art					
Project Manager 0 04/25/2014 Project Manager 0 04/25/2014 Jerenty Savage Mechanical Engineer 2 05/08/2014 Pad Print Add Per Pad Print Matte	Project Manager	Date	04/25/2014	Approvals	Signature	Date	Revision	Date	Description
Ful Size Product Line Manager 1 1 6 508/2014 Pentone 10364 OA Rep 2 05/08/2014 Pad Print Pad P	Full Size Product Line Manager 1 060082014 Jeromy Savage Mechanical Engineer 2 060082014 Pantone 10394 QA Rep Partone 10394 Partone 10395 QA Rep Matte 6 0577022014 6 077022014 7 127042015	Drawing #	,	Project Manager			0	04/25/2014	Original
Jeremy Savage Mechanical Engineer 2 05/08/2014 Pantone 10394	Jeremy Savage Mechanical Engineer 2 05/08/2014 Pantone 10394	Scale	Full Size	Product Line Manager			-		Changed FCC and IC numbers
Partone 10394 OA Rep 3 05/14/2014 Pad Print 4 05/19/2014 Matte 6 07/02/2014 6 07/02/2014 7 12/04/2015 8 12/19/2015	Partone 10394 OA Rep 3 05/14/2014 Pad Print Matte	Prepared by	Jeremy Savage	Mechanical Engineer			2	05/08/2014	Added desiged in USA / China, updated FCC paragraph
Pad Print 3 05/14/2014 Matte 4 05/19/2014	Pad Print Matte	Color	Pantone 10394	QA Rep					added check logo, removed UL and check logo
Matte 4 05/19/2014	Matte 4 05/19/2014	Process	Pad Print				3		Added TUV, Check mark RCM,
5 0626/2014 6 07/02/2014 7 12/04/2015 8 12/15/2015	5 0628/2014 6 07/02/2014 7 12/04/2015 8 12/15/2015	Finish	Matte				4	05/19/2014	Changed 10395 to 8002, edited FCC and IC numbers,
5 06/28/2014 Increased FCC fort size, Replaced 80/2 with 10394 Replaced 80/2 with 10394 6 07/02/2014 Flipped Power and Status, increased size of FCC paragraph, removed Polk from mox 7 7 12/04/2015 Changed FCC / IC dis, Polk SBI Plus Sub 8 12/15/2015 Removed ID from IC Number	5 06/26/2014 Increased FCC (on the control of	Notes	ı						removed check and energy star graphics
6 07022014 Peplaced 8002 with 10394 6 17022014 Pepla Power and Status, Increased size of FOC paragraph, removed Polk from moc 7 1204/2015 Charged FCC / Icl siz. Polk SB1 Plus Sub 8 12/152015 Removed ID from IC Number	Replaced 8002 with Removed ID from Removed						2	06/26/2014	Increased FCC font size,
6 07/02/2014 Fipped Power and Status, Increased size of FCC paragraph, removed Polk from mox 12/04/2015 Changed FCC / IC ids., Polk SB1 Plus Sub 8 12/19/2015 Removed ID from IC Number	6 07/02/2014 Flipped Power and 7 12/04/2015 Changed FCC / IC 8 12/15/2015 Removed ID from								Replaced 8002 with 10394
7 12/04/2015 Changed FCC / IC ids , Polk SB1 Plus Sub 8 12/15/2015 Removed ID from IC Number	7 12/04/2015 Changed FCC / IC						9	07/02/2014	Flipped Power and Status, Increased size of FCC paragraph, removed Polk from model I
							7	12/04/2015	Changed FCC / IC ids , Polk SB1 Plus Sub
							80	12/15/2015	Removed ID from IC Number