2. Internal Photograph of EUT

Brand Name: Maestro; Model Name: E206XT


Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 9 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01



Report No.: EP531712




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT

Page Number : 10 of 26 Report Issued Date : Apr. 23, 2015

Report Version : Rev. 01



Report No.: EP531712




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT

Page Number : 11 of 26 Report Issued Date : Apr. 23, 2015 Report Version : Rev. 01



Report No.: EP531712




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT

Page Number : 12 of 26 Report Issued Date : Apr. 23, 2015 Report Version : Rev. 01



Report No.: EP531712




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 13 of 26
Report Issued Date : Apr. 23, 2015

Report Version : Rev. 01



Report No.: EP531712




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT

Page Number : 14 of 26 Report Issued Date : Apr. 23, 2015 Report Version : Rev. 01




Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT


Page Number : 15 of 26 Report Issued Date : Apr. 23, 2015 Report Version : Rev. 01

Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 16 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01


Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 17 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01



Report No.: EP531712




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT

Page Number : 18 of 26 Report Issued Date : Apr. 23, 2015 Report Version : Rev. 01



Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT


Page Number : 19 of 26 Report Issued Date : Apr. 23, 2015 Report Version : Rev. 01

Report No.: EP531712




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 20 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01

Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 21 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01

Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 22 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01



Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT

Page Number : 23 of 26 Report Issued Date : Apr. 23, 2015

: Rev. 01 Report Version

Report No.: EP531712



Brand Name: Maestro; Model Name: E206XT

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT

Page Number : 24 of 26 Report Issued Date : Apr. 23, 2015 : Rev. 01 Report Version

Report No.: EP531712



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 25 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01

Report No.: EP531712



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WN6-E206XT Page Number : 26 of 26
Report Issued Date : Apr. 23, 2015
Report Version : Rev. 01