



attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

To Whom It May Concern:

The BC91005002 FCC ID: WONBC91005002 Does not require any Tuning procedures in order to function.

The device operate within the 902-928MHz ISM band. There are no trimmers, variable capacitors or any other such components within the unit.

Please contact me if there is any information you may need.

Sincerely,

Lior Bilia HW engineer

Precyse Technologies Inc Tel: 972-3-9227093

Mobile: 972-54-2467600 Fax: 972-3-9227515