



attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

November 3, 2013

To Whom It May Concern:

Model: BS91103000

FCC ID: WONBS91103001

Do not require any Tuning procedures in order to function. The devices operate within the 902-928MHz ISM band. There are no trimmers, variable capacitors or any other such components within the unit. Please contact me if there is any information you may need.

Sincerely,

Yossi Nurok HW engineer

Precyse Technologies Inc

Yossi Nurok

Tel: 972-3-9227093 Mobile: 972-54-4482062 Fax: 972-3-9227515