

Visonic Ltd. 24 Habarzel Street P.O.Box 22020 Tel-Aviv 69710, Israel

Tele: +972 3 645 6789 Fax: +972 3 645 6788 www.visonic.com

Date: November 23, 2015

Attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

To Whom It May Concern:

The Visonic Ltd., Glass Break Detector, Model GB-502 PG2,

FCC ID: WP3GB502PG2, and label are so small that it cannot include the statement specified in FCC Part 15 Subpart A, Section 15.19 (a) (3)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Sincerely,

Zuri Rubin, Certification Manager.

. , 0/3 pre/)