
IC: 8014A-CWAP


10. **SETUP PHOTOS**

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP





END OF REPORT