Test setup photographs Transmitter





Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Revision 1

Digital Ally, Inc.

Model: DWM1000RMT (DWMRMT1) Test #:080921 SN: 0490-0009 Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup DWMRMT1

FCC ID#: WPZ-DWMRMT1 IC: 7945A-DWMRMT1

Page 1 of 4





Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Digital Ally, Inc.

Model: DWM1000RMT (DWMRMT1)
Test #:080921 SN: 0490-0009
Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup DWMRMT1

FCC ID#: WPZ-DWMRMT1 IC: 7945A-DWMRMT1

Page 2 of 4





Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Digital Ally, Inc.

Model: DWM1000RMT (DWMRMT1)
Test #:080921 SN: 0490-0009
Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup DWMRMT1

FCC ID#: WPZ-DWMRMT1 IC: 7945A-DWMRMT1

Page 3 of 4





Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Revision 1

Digital Ally, Inc.

Model: DWM1000RMT (DWMRMT1) Test #:080921 SN: 0490-0009 Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup DWMRMT1

FCC ID#: WPZ-DWMRMT1 IC: 7945A-DWMRMT1

Page 4 of 4