Test setup photographs





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1


Digital Ally Model: VuLink2 Test #: 161121

Test to: CFR47 (15.247), RSS-210

File: Vulink2 TSup

S/N: 09502057 FCC ID: WPZ-VULINK2 IC: 7945A-VULINK2 Date: January 10, 2017

Page 1 of 5





Phone/Fax: (913) 837-321 Revision 1 Digital Ally Model: VuLink2 Test #: 161121

Test to: CFR47 (15.247), RSS-210

File: Vulink2 TSup

S/N: 09502057

FCC ID: WPZ-VULINK2 IC: 7945A-VULINK2 Date: January 10, 2017

Page 2 of 5





Revision 1

Digital Ally Model: VuLink2 Test #: 161121

Test to: CFR47 (15.247), RSS-210


File: Vulink2 TSup

S/N: 09502057

FCC ID: WPZ-VULINK2 IC: 7945A-VULINK2 Date: January 10, 2017

Page 3 of 5





Revision 1

Digital Ally Model: VuLink2 Test #: 161121

Test to: CFR47 (15.247), RSS-210

File: Vulink2 TSup

S/N: 09502057

FCC ID: WPZ-VULINK2 IC: 7945A-VULINK2 Date: January 10, 2017

Page 4 of 5



Revision 1

Digital Ally Model: VuLink2 Test #: 161121

Test to: CFR47 (15.247), RSS-210

File: Vulink2 TSup

S/N: 09502057

FCC ID: WPZ-VULINK2 IC: 7945A-VULINK2 Date: January 10, 2017

Page 5 of 5