1170.0121.00.00	RMT Final Test and Calibration Procedure	Digital Ally, Inc.
Prepared by: <u>Jeff Burgess</u>		
Approved by: Yancy Scroggins		
Effective Date: August 13, 2008		

## **RMT/ICT Final Test and Calibration Procedure**

Prior to implementing the procedure, read this document in its entirety.

- **1.0** Start "DWM1000 Test.exe" application on test station.
- Plug RMT or ICT Digital and RF PCB assembly (DWM1000-01 and DWM1000-02 or DWM1000-04 and DWM1000-05) into DWM1000-93 test fixture.
- 3.0 Move the DWM1000-93 power switch to the ON position.
- **4.0** Select the "Start" button in the "DWM1000 Test" application window.
- 5.0 If the test result is "FAILED" move the DWM1000-93 power switch to the "OFF" position and submit the RMT assembly for repair.
- 6.0 If the test is "SUCCESSFUL", move the DWM1000-93 power switch to the "OFF" position and apply the Serial Number/FCC ID Label.

Rev00	ECO – na	Note: Initial Release

1170.0121.00.00 Page 1 of 1