
## External photographs of equipment under test





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Digital Ally

Model: FirstVu HD One Test #: 160429 160818

Test to: CFR47 15C, RSS-Gen RSS-210 File: FirstVuHD1 Short Term Conf ExtPh

SN: O5D8-0026

FCC ID: WPZ-FIRSTVU1 IC: 7945A-FIRSTVU1 Date: August 22, 2016

Page 1 of 3





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Digital Ally Model: FirstVu HD One Test #: 160429 160818

Test to: CFR47 15C, RSS-Gen RSS-210 File: FirstVuHD1 Short Term Conf ExtPh SN: O5D8-0026

FCC ID: WPZ-FIRSTVU1 IC: 7945A-FIRSTVU1 Date: August 22, 2016

Page 2 of 3





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Digital Ally Model: FirstVu HD One Test #: 160429 160818

Test to: CFR47 15C, RSS-Gen RSS-210 File: FirstVuHD1 Short Term Conf ExtPh SN: O5D8-0026

FCC ID: WPZ-FIRSTVU1 IC: 7945A-FIRSTVU1 Date: August 22, 2016

Page 3 of 3