Test report No.
 : 12858370S-A-R2


 Page
 : 36 of 38

 Issued date
 : June 28, 2019

 FCC ID
 : WQYMTBLE1

# **APPENDIX 3: Photographs of test setup**

# **Conducted Emission**





## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

 Test report No.
 : 12858370S-A-R2


 Page
 : 37 of 38


 Issued date
 : June 28, 2019

 FCC ID
 : WQYMTBLE1

# **Radiated Spurious Emission**


### Below 1 GHz






Above 1 GHz










## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

: 12858370S-A-R2 Test report No. : 38 of 38 Page : June 28, 2019 : WQYMTBLE1 **Issued date** FCC ID

# **Pre-check of Worst Case Position**



Y-axis



**Z**-axis



**End of Report** 

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401