



131992\_6.JPG: RFU620-10101, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 1 of 13






131992\_7.JPG: RFU620-10101, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 2 of 13






131992\_10.JPG: RFU620-10101, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 3 of 13






131992\_8.JPG: RFU620-10101, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 4 of 13





131992\_9.JPG: RFU620-10101, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 5 of 13






131992\_11.JPG: RFU620-10101, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 6 of 13





131992\_13.JPG: RFU620-10101, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 7 of 13






131991\_2.JPG: RFU620-10501, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 8 of 13





131991\_5.JPG: RFU620-10501, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 9 of 13






131991\_3.JPG: RFU620-10501, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 10 of 13





131991\_4.JPG: RFU620-10501, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 11 of 13






131991\_6.JPG: RFU620-10501, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 12 of 13





131991\_7.JPG: RFU620-10501, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 20 June 2013
 Order No.:
 13-111991 and 13-111992
 page 13 of 13