



113961\_I.JPG: EUT with internal antenna, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 1 of 10





113961\_o.JPG: EUT with external patch antenna, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 2 of 10






113961\_w.JPG: EUT with external ULORA antenna, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 3 of 10






113961\_h1.JPG: EUT with internal antenna, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 4 of 10






113961\_t.JPG: EUT with external patch antenna, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 5 of 10






113961\_y.JPG: EUT with external ULORA antenna, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 6 of 10





113961\_d1.JPG: EUT with internal antenna, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 7 of 10





113961\_c1.JPG: EUT with external patch antenna, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 8 of 10






113961\_z.JPG: EUT with external ULORA antenna, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 9 of 10





113961\_j1.JPG: Test set-up shielded room

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961

page 10 of 10