



152541_1a.JPG: RFU650-10101, 3-D-view 1

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541
 page 1 of 4





152541_1b.JPG: RFU650-10101, 3-D-view 2

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541

 page 2 of 4





152541_1q.JPG: RFU650-10101, 3-D-view 3

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541
 page 3 of 4





152541_1c.JPG: RFU650-10101, connector view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541
 page 4 of 4