



Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A5

Report Version

: Rev. 01

Report No.: FR520334AL







Report No.: FR520334AL

Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report Report No.: FR520334AL

## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A5 Report Version : Rev. 01




FCC Test Report

Report No.: FR520334AL

## For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5

Report Version


: Rev. 01




FCC Test Report

Report No.: FR520334AL

## For radiated emissions above 1GHz



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5 Report Version : Rev. 01






Report No.: FR520334AL



EUT take a close-up



EUT take a close-up


SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A5 Report Version : Rev. 01



FCC Test Report No.: EP520334

## APPENDIX B. Photographs of EUT






SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B1 of B3


Report Version : Rev. 01







Report No.: EP520334




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B2 of B3
Report Version : Rev. 01



FCC Test Report No.: EP520334



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B3 of B3
Report Version : Rev. 01