
3. Internal Photograph of EUT

Brand Name: EPSON / Model Name: H695A

Report No.: EP441033



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 7 of 22 Report Issued Date : May 13, 2014

Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2-STM7C24EE IC: 10462A-STM7C24EE

Page Number : 8 of 22 Report Issued Date : May 13, 2014

Report Version : Rev. 01


Report No.: EP441033



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 9 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01




Report No.: EP441033



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2-STM7C24EE IC: 10462A-STM7C24EE

Page Number : 10 of 22 Report Issued Date : May 13, 2014 Report Version : Rev. 01


Brand Name: EPSON / Model Name: H695A



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2-STM7C24EE IC: 10462A-STM7C24EE

Page Number : 11 of 22 Report Issued Date : May 13, 2014 Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2-STM7C24EE IC: 10462A-STM7C24EE

Page Number : 12 of 22 Report Issued Date : May 13, 2014 Report Version : Rev. 01







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2-STM7C24EE IC: 10462A-STM7C24EE


Page Number : 13 of 22 Report Issued Date : May 13, 2014 Report Version : Rev. 01

Report No.: EP441033



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 14 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2-STM7C24EE IC: 10462A-STM7C24EE


Page Number : 15 of 22 Report Issued Date : May 13, 2014 Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 16 of 22 Report Issued Date : May 13, 2014 Report Version : Rev. 01

Report No.: EP441033




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 17 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01

Report No.: EP441033



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 18 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01


Report No.: EP441033




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 19 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01

Report No.: EP441033



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 20 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 21 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01



Report No.: EP441033



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS2- STM7C24EE IC: 10462A- STM7C24EE Page Number : 22 of 22
Report Issued Date : May 13, 2014
Report Version : Rev. 01