

Report No.: HA240604-01A

Appendix D. Product Photos Sample 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : D1 of D3
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



Variant FCC HAC RF Emissions Test Report

Sample 2



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : D2 of D3
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

Report No.: HA240604-01A



Variant FCC HAC RF Emissions Test Report

Report No.: HA240604-01A

Sample 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : D3 of D3
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



Report No.: HA240604-01A


Appendix E. Sample 1: **Test Setup Photos**



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : E1 of E3 Report Issued Date: Apr. 24, 2013 Report Version : Rev. 03



Sample 2:



Front View



Left Side View



Right Side View

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : E2 of E3
Report Issued Date : Apr. 24, 2013

Report No.: HA240604-01A

Report Version : Rev. 03



Sample 3:



Front View



Left Side View



Right Side View

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : E3 of E3
Report Issued Date : Apr. 24, 2013

Report No.: HA240604-01A

Report Version : Rev. 03