

Appendix C. Product Photos

Sample 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO620 Page Number : C1 of C2
Report Issued Date : Apr. 09, 2013
Report Version : Rev. 02

Report No.: HA312204B



Report No.: HA312204B

Sample 2




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO620 Page Number : C2 of C2
Report Issued Date : Apr. 09, 2013
Report Version : Rev. 02



Appendix D. Test Setup Photos Sample 1:



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO620 Page Number : D1 of D2
Report Issued Date : Apr. 09, 2013
Report Version : Rev. 02


Report No.: HA312204B




Sample 2:



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO620 Page Number : D2 of D2 Report Issued Date : Apr. 09, 2013

Report No.: HA312204B

Report Version : Rev. 02