

Report No.: FR533002-01C

# Appendix C. Setup Photographs

### <Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : C1 of C3
Report Issued Date : Jul. 30, 2015
Report Version : Rev. 01




#### <Radiated Emission>

#### Z Plane for WLAN 2.4GHz 802.11b/g without Cradle

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : C2 of C3
Report Issued Date : Jul. 30, 2015
Report Version : Rev. 01


Report No.: FR533002-01C




# Report No.: FR533002-01C

## Z Plane for WLAN 2.4GHz 802.11n HT20 with Cradle

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : C3 of C3 Report Issued Date: Jul. 30, 2015 Report Version : Rev. 01