


Report No.: FA931114-03

Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO341G Page Number : D1 of D1
Report Issued Date : Jan. 05, 2010
Report Version : Rev. 01




Report No.: FA931114-03

Appendix E. **Test Setup Photos**



Right Cheek



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO341G Page Number : E1 of E1 Report Issued Date: Jan. 05, 2010

Report Version : Rev. 01