1. External Photograph of EUT

Brand Name: doro; Model Name: DSB-0020

Report No.: EP533002-12



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 1 of 38
Report Issued Date : Mar. 15, 2016



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 2 of 38





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 3 of 38






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 4 of 38





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 5 of 38 Report Issued Date : Mar. 15, 2016





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 6 of 38

2. Photograph of Accessory

Brand Name: doro; Model Name: DSB-0020

Report No.: EP533002-12

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	doro
	Model Name	BUUS050100-C00
Battery	Brand Name	doro
	Model Name	BDA-2000A
Cradle	Brand Name	doro
	Model Name	NA
USB Cable	Signal Line Type	1.52m, shielded cable, without core
Earphone	Signal Line Type	1.18m, non-shielded cable, without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 7 of 38
Report Issued Date : Mar. 15, 2016





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 8 of 38
Report Issued Date : Mar. 15, 2016

Report No.: EP533002-12



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U

: 9 of 38 Page Number


Report No.: EP533002-12

Brand Name: doro; Model Name: DSB-0020



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 10 of 38
Report Issued Date : Mar. 15, 2016
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 11 of 38
Report Issued Date : Mar. 15, 2016
Report Version : Rev. 01



Report No.: EP533002-12



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 12 of 38 Report Issued Date : Mar. 15, 2016

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 13 of 38
Report Issued Date : Mar. 15, 2016

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO824U Page Number : 14 of 38
Report Issued Date : Mar. 15, 2016