



Page Number : A19 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5




Page Number : A20 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5




Page Number : A21 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5



Page Number : A22 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5



Page Number : A23 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01


Report Template No.: BU5-FGLTE Version 1.5

#### **Conducted Spurious Emission**




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : A24 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : A25 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A26 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : A27 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01


Report Template No.: BU5-FGLTE Version 1.5



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : A28 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5



Page Number : A29 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5

## Frequency Stability

Test (	Conditions	LTE Band 7 (QPSK) / Middle Channel	Limit
_		BW 10MHz	Note 2.
Temperature (°C)	Voltage (Volt)	Deviation (ppm)	Result
50	Normal Voltage	0.0013	
40	Normal Voltage	0.0000	
30	Normal Voltage	0.0022	
20(Ref.)	Normal Voltage	0.0000	
10	Normal Voltage	0.0004	
0	Normal Voltage	0.0007	
-10	Normal Voltage	0.0009	PASS
-20	Normal Voltage	0.0002	
-30	Normal Voltage	0.0014	
20	Maximum Voltage	0.0021	
20	Normal Voltage	0.0017	
20	Battery End Point	0.0013	

#### Note:

- 1. Normal Voltage = 3.8V. ; Battery End Point (BEP) = 3.6 V.; Maximum Voltage =4.2 V
- 2. The frequency fundamental emissions stay within the authorized frequency block based on the frequency deviation measured is small.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : A30 of A30
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5

## **Appendix B. Test Results of Radiated Test**



	LTE Band 7 / 5MHz (Average)												
Channal	Modulation	RB		Horiz	ontal	Vert	ical						
Channel	Wodulation	Size	Offset	EIRP(dBm)	EIRP(W)	EIRP(dBm)	EIRP(W)						
Lowest		1	12	25.59	0.3622	25.42	0.3483						
Middle	QPSK	1	12	24.67	0.2931	24.37	0.2735						
Highest		1	12	26.12	0.4093	25.56	0.3597						
Lowest		1	0	24.86	0.3062	24.68	0.2938						
Middle	16QAM	1	0	25.65	0.3673	24.96	0.3133						
Highest		1	0	24.55	0.2851	24.15	0.2600						
Limit	EIRI	o < 2W		Res	sult	PAS	SS						

	LTE Band 7 / 10MHz (Average)												
Channal	Madulation	RB		Horiz	ontal	Vertical							
Channel	Modulation	Size	Offset	EIRP(dBm)	EIRP(W)	EIRP(dBm)	EIRP(W)						
Lowest		1	0	25.58	0.3614	25.38	0.3451						
Middle	QPSK	1	25	24.72	0.2965	24.36	0.2729						
Highest		1	25	26.41	0.4375	25.81	0.3811						
Lowest		1	0	25.00	0.3162	24.69	0.2944						
Middle	16QAM	1	25	26.26	0.4227	25.67	0.3690						
Highest		1	25	25.26	0.3357	24.62	0.2897						
Limit	EIRI	o < 2W		Res	sult	PAS	PASS						

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : B1 of B4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5

	LTE Band 7 / 15MHz (Average)												
Channel	Modulation	RB		Horizo	ontal	Vert	ical						
Channel	Wiodulation	Size	Offset	EIRP(dBm)	EIRP(W)	EIRP(dBm)	EIRP(W)						
Lowest		1	0	25.66	0.3681	25.35	0.3428						
Middle	QPSK	1	37	24.92	0.3105	24.60	0.2884						
Highest		1	0	25.99	0.3972	25.67	0.3690						
Lowest		1	0	25.51	0.3556	25.30	0.3388						
Middle	16QAM	1	0	26.23	0.4198	25.55	0.3589						
Highest		1	0	25.54	0.3581	24.87	0.3069						
Limit	EIRP < 2W			Res	ult	PASS							

	LTE Band 7 / 20MHz (Average)												
Channal	Madulation	RB		Horizo	ontal	Vert	ical						
Channel	Modulation	Size	Offset	EIRP(dBm)	EIRP(W)	EIRP(dBm)	EIRP(W)						
Lowest		1	0	25.56	0.3597	25.35	0.3428						
Middle	QPSK	1	0	24.91	0.3097	24.65	0.2917						
Highest		1	0	25.92	0.3908	25.70	0.3715						
Lowest		1	0	24.93	0.3112	25.20	0.3311						
Middle	16QAM	1	0	26.34	0.4305	25.47	0.3524						
Highest		1	49	25.02	0.3177	24.40	0.2754						
Limit	EIRI	o < 2W		Res	sult	PAS	PASS						

Page Number : B2 of B4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5

## **Radiated Spurious Emission**

	LTE Band 7 / 5MHz / QPSK / RB Size 1 Offset 0														
Channel	Frequency (MHz)	ERP (dBm)	Limit ( dBm )	Over Limit ( dB )	SPA Reading (dBm)	S.G. Power (dBm)	TX Cable loss ( dB )	TX Antenna Gain (dBi)	Polarization (H/V)						
	5066	-48.50	-25	-23.50	-35.12	-55.06	2.41	8.97	Н						
	7598	-42.54	-25	-17.54	-37.86	-51.54	2.86	11.86	Н						
Middle	10130	-56.61	-25	-31.61	-52.00	-65.51	3.21	12.11	Н						
Middle	5066	-52.83	-25	-27.83	-39.43	-59.39	2.41	8.97	V						
	7598	-50.61	-25	-25.61	-43.45	-59.61	2.86	11.86	V						
	10130	-57.72	-25	-32.72	-53.24	-66.62	3.21	12.11	V						

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

	LTE Band 7 / 10MHz / QPSK / RB Size 1 Offset 0													
Channel	Frequency ( MHz )	EIRP (dBm)	Limit ( dBm )	Over Limit ( dB )	SPA Reading (dBm)	S.G. Power ( dBm )	TX Cable loss ( dB )	TX Antenna Gain (dBi)	Polarization (H/V)					
	5060	-46.30	-25	-21.30	-33.55	-52.86	2.41	8.97	Н					
	7592	-40.76	-25	-15.76	-36.46	-49.76	2.86	11.86	Н					
Middle	10124	-57.84	-25	-32.84	-53.23	-66.74	3.21	12.11	Н					
Middle	5060	-50.31	-25	-25.31	-37.81	-56.87	2.41	8.97	V					
	7592	-47.80	-25	-22.80	-41.99	-56.80	2.86	11.86	V					
	10124	-56.02	-25	-31.02	-51.54	-64.92	3.21	12.11	V					

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

	LTE Band 7 / 15MHz / QPSK / RB Size 1 Offset 0													
Channel	Frequency ( MHz )	EIRP (dBm)	Limit ( dBm )	Over Limit ( dB )	SPA Reading (dBm)	S.G. Power ( dBm )	TX Cable loss ( dB )	TX Antenna Gain (dBi)	Polarization (H/V)					
	5054	-46.89	-25	-21.89	-33.98	-53.45	2.41	8.97	Н					
	7586	-41.03	-25	-16.03	-36.69	-50.03	2.86	11.86	Н					
Middle	10112	-57.96	-25	-32.96	-53.35	-66.86	3.21	12.11	Н					
Middle	5054	-49.11	-25	-24.11	-36.83	-55.67	2.41	8.97	V					
	7586	-47.33	-25	-22.33	-41.57	-56.33	2.86	11.86	V					
	10112	-56.37	-25	-31.37	-51.89	-65.27	3.21	12.11	V					

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : B3 of B4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5

	LTE Band 7 / 20MHz / QPSK / RB Size 1 Offset 0													
Channel	Frequency (MHz)	EIRP (dBm)	Limit ( dBm )	Over Limit ( dB )	SPA Reading (dBm)	S.G. Power ( dBm )	TX Cable loss ( dB )	TX Antenna Gain (dBi)	Polarization (H/V)					
	5054	-44.29	-25	-19.29	-32.00	-50.85	2.41	8.97	Н					
	7580	-39.35	-25	-14.35	-35.19	-48.35	2.86	11.86	Н					
Middle	10106	-58.54	-25	-33.54	-53.93	-67.44	3.21	12.11	Н					
Middle	5054	-48.92	-25	-23.92	-36.66	-55.48	2.41	8.97	V					
	7580	-47.18	-25	-22.18	-41.44	-56.18	2.86	11.86	V					
	10106	-57.09	-25	-32.09	-52.61	-65.99	3.21	12.11	V					

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : B4 of B4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5

# Appendix D. Photographs of EUT

Please refer to Sporton report number EP570906-04 which is issued separately.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : D1 of D1
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5