3. Internal Photograph of EUT

Brand Name: doro; Model Name: Doro PhoneEasy 622

Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 17 of 39 Report Issued Date : Apr. 22, 2014





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 18 of 39
Report Issued Date : Apr. 22, 2014





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WS5DORO622

: 19 of 39 Page Number Report Issued Date : Apr. 22, 2014 Report Version : Rev. 01

Report No.: EP431101

Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 20 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01


Report No.: EP431101



TEL: 86-755- 3320-2398 FCC ID: WS5DORO622


Page Number : 21 of 39
Report Issued Date : Apr. 22, 2014

Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 22 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01


Report No.: EP431101




TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 23 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01


Brand Name: doro; Model Name: Doro PhoneEasy 622

Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 24 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 25 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01



Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622


: 26 of 39 Page Number Report Issued Date : Apr. 22, 2014

: Rev. 01

Report Version



Report No.: EP431101




TEL: 86-755-3320-2398 FCC ID: WS5DORO622


Page Number : 27 of 39 Report Issued Date : Apr. 22, 2014




Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 28 of 39 Report Issued Date : Apr. 22, 2014 Report Version : Rev. 01




Brand Name: doro; Model Name: Doro PhoneEasy 622



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 29 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01


Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 30 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01



Report No.: EP431101



TEL: 86-755- 3320-2398 FCC ID: WS5DORO622


Page Number : 31 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01

Report No.: EP431101




TEL: 86-755- 3320-2398 FCC ID: WS5DORO622 Page Number : 32 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01

Report No.: EP431101




TEL: 86-755- 3320-2398 FCC ID: WS5DORO622 Page Number : 33 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01

Report No.: EP431101



TEL: 86-755- 3320-2398 FCC ID: WS5DORO622 Page Number : 34 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01


Report No.: EP431101



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 35 of 39
Report Issued Date : Apr. 22, 2014


Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622

Page Number : 36 of 39 Report Issued Date : Apr. 22, 2014 Report Version : Rev. 01


Report No.: EP431101



TEL: 86-755- 3320-2398 FCC ID: WS5DORO622 Page Number : 37 of 39
Report Issued Date : Apr. 22, 2014
Report Version : Rev. 01




Report No.: EP431101



TEL: 86-755-3320-2398 FCC ID: WS5DORO622 Page Number : 38 of 39 Report Issued Date : Apr. 22, 2014 : Rev. 01 Report Version

Report No.: EP431101

Brand Name: doro; Model Name: Doro PhoneEasy 622



TEL: 86-755- 3320-2398 FCC ID: WS5DORO622 Page Number : 39 of 39
Report Issued Date : Apr. 22, 2014