## 3. Internal Photograph of EUT

Model Name: Doro PhoneEasy 338gsm

Report No.: EP931114-02



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 14 of 27 Issued Date : Jan. 05, 2010 Report Version : Rev. 01

Madal Names Dana BhanaFass 220 anns

Report No.: EP931114-02



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 15 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 16 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01






TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 17 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-02




TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 18 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-02



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 19 of 27 Issued Date : Jan. 05, 2010 Report Version : Rev. 01

Report No.: EP931114-02



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 20 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM

Page Number : 21 of 27 Issued Date : Jan. 05, 2010 Report Version: Rev. 01




TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM

Page Number : 22 of 27 Issued Date : Jan. 05, 2010 Report Version : Rev. 01

Report No.: EP931114-02



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 23 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 24 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-02




TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 25 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-02



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 26 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-02



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO338G IC: 8175A-DORO338GSM Page Number : 27 of 27
Issued Date : Jan. 05, 2010
Report Version : Rev. 01