


Report No.: FA952506

Appendix D - Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO410G Report Issued Date : Jul. 11, 2009 Report Version : Rev. 01



Report No.: FA952506

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO410G Report Issued Date : Jul. 11, 2009 Report Version : Rev. 01



Report No.: FA952506

Appendix E - Test Setup Photos



Right Cheek

Right Tilted







Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO410G Report Issued Date : Jul. 11, 2009 Report Version : Rev. 01