3. Internal Photograph of EUT

Model Name: Doro PhoneEasy 341gsm

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 14 of 26 Issued Date : Jan. 05, 2010 Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 15 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-03




TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 16 of 26 Issued Date : Jan. 05, 2010 Report Version : Rev. 01

Report No.: EP931114-03




TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 17 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 18 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 19 of 26 Issued Date : Jan. 05, 2010 Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 20 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-03



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 21 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 22 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM

Page Number : 23 of 26 Issued Date : Jan. 05, 2010 Report Version: Rev. 01

Report No.: EP931114-03




TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 24 of 26 Issued Date : Jan. 05, 2010 Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 25 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01

Report No.: EP931114-03



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: WS5DORO341G IC: 8175A-DORO341GSM Page Number : 26 of 26
Issued Date : Jan. 05, 2010
Report Version : Rev. 01