

Appendix E. SAR Test Setup Photos



Left Tilted (Flip Open)

Front, Test Separation 1.5 cm (Flip Close)

Report No.: FA431101-01



Back, Test Separation 1.5 cm (Flip Close)

SPORTON INTERNATIONAL (SHENZHEN) INC. TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595


FCC ID: WS5DORO623 Page E1 of E4


: Apr. 29, 2014 Issued Date Form version.

: 140305

Variant FCC SAR Test Report


GSM1900 Band:





Report No.: FA431101-01

Left Cheek (Flip Open)



Left Cheek SAR in mouth area (Flip Open)


SPORTON INTERNATIONAL (SHENZHEN) INC. TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595


FCC ID: WS5DORO623 Page

Issued Date : Apr. 29, 2014 Form version. : 140305




WCDMA Band V:






Report No.: FA431101-01


Right Cheek (Flip Open)





Right Tilted (Flip Open)





Left Cheek (Flip Open)

 ${\it SPORTON\ INTERNATIONAL\ (SHENZHEN)\ INC.}$

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595 FCC ID: WS5DORO623

Issued Date : Apr. 29, 2014 Form version. : 140305

Page E3 of E4



Variant FCC SAR Test Report



Left Cheek SAR in mouth area (Flip Open)

Note: Chose the shortest distance of SAR peak location to phantom surface between right cheek and left cheek to perform Mouth area SAR testing.

Report No.: FA431101-01

 SPORTON INTERNATIONAL (SHENZHEN) INC.
 Issued Date
 : Apr. 29, 2014

 TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595
 Form version.
 : 140305

FCC ID: WS5DORO623 Page E4 of E4