

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : C1 of C3
Report Issued Date : Jul. 30, 2015
Report Version : Rev. 01


Report No.: FR533002C




<Radiated Emission>

Z Plane for WLAN 2.4GHz 802.11b/g with Cradle

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : C2 of C3
Report Issued Date : Jul. 30, 2015
Report Version : Rev. 01

Report No.: FR533002C




Z Plane for WLAN 2.4GHz 802.11n HT20 without Cradle

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : C3 of C3
Report Issued Date : Jul. 30, 2015
Report Version : Rev. 01

Report No.: FR533002C