


Report No.: FA931114-02

## Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO338G Page Number : D1 of D2
Report Issued Date : Jan. 05, 2010
Report Version : Rev. 01



Report No. : FA931114-02

## Appendix E. **Test Setup Photos**



**Right Cheek** 



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO338G Page Number : E1 of E1 Report Issued Date: Jan. 05, 2010 Report Version : Rev. 01