


Report No.: FG952506


Appendix B. Setup Photographs

<Radiated Emission>

WWAN Link



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO410G

: B1 of B3 Page Number Report Issued Date: Jul. 13, 2009 Report Version : Rev. 01






Report No.: FG952506



Remote View

BT Link



Front View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO410G Page Number : B2 of B3
Report Issued Date : Jul. 13, 2009
Report Version : Rev. 01






Report No. : FG952506

Rear View





Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WS5DORO410G Page Number : B3 of B3
Report Issued Date : Jul. 13, 2009
Report Version : Rev. 01