3. Internal Photograph of EUT

Brand Name: doro / Model Name: DSB-0010


Report No.: EP570906-04



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 30 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01



Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010

: 31 of 49 Page Number Report Issued Date : Aug. 12, 2016 Report Version : Rev. 01



Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010

: 32 of 49 Page Number Report Issued Date : Aug. 12, 2016 Report Version : Rev. 01



Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010

: 33 of 49 Page Number Report Issued Date : Aug. 12, 2016 Report Version : Rev. 01



Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010

: 34 of 49 Page Number Report Issued Date : Aug. 12, 2016



Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010

: 35 of 49 Page Number Report Issued Date : Aug. 12, 2016 Report Version : Rev. 01



Report No.: EP570906-04



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010


: 36 of 49 Page Number Report Issued Date : Aug. 12, 2016

Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 37 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 38 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 39 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 40 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 41 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 42 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 43 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 44 of 49
Report Issued Date : Aug. 12, 2016

Report No.: EP570906-04



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 45 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01

Report No.: EP570906-04



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 46 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01



Report No.: EP570906-04




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010

Page Number : 47 of 49 Report Issued Date : Aug. 12, 2016




Report No.: EP570906-04



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010

: 48 of 49 Page Number Report Issued Date : Aug. 12, 2016

Report No.: EP570906-04



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : 49 of 49
Report Issued Date : Aug. 12, 2016
Report Version : Rev. 01